



# 9990

Fire Door Top Gap Solution—Up To 90 Minutes

## PRODUCT CUT SHEET


**UL Certified for Door Top Gaps—Measuring up to  $\frac{1}{2}$ ".**



- 90-Minute Rated—for use on UL10B and UL10C Wood or Hollow Metal Fire Doors
- No need to move hardware at the top of the door
- Works on doors with Parallel arm closers
- Patent Pending
- Available in 36" and 48" Lengths
- Brushed stainless steel
- End caps furnished standard
- Non-Handed

### PRODUCT CONSISTS OF:

- #304 Brushed Stainless Steel Flat Plate - Pull Side
- #304 Brushed Stainless Steel Intumescent Cap—Push Side
- #304 Brushed Stainless Steel End Caps
- #6 X  $\frac{3}{4}$ " Stainless Steel SMS Furnished



NGP-FDA-9990-PCS-1119-A